

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representative	es Present During the Inspection:	
Company	Russell Hardy	
OGM	Steve Demczak Environmental Scientist III	

Inspection Report

Permit Number:	C0150015		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, August 17, 2005		
Start Date/Time:	8/17/2005 10:00:00 AM		
End Date/Time:	8/17/2005 2:00:00 PM		
Last Inspection:	Monday, August 15, 2005		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Warm, Upper 80's InspectionID Report Number: 697

Accepted by: pgrubaug

Tuesday, August 23, 2005

Date

9/1/2005

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: **EMERY DEEP MINE**

Address: PO BOX 566, SESSER IL 62884

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

5,060.00	Total Permitted		
289.60	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Types of Operations Mineral Ownership

✓ Federal	Underground
State	Surface
County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions: Emery Deep has one permit condition. The permittee must submit water quality data in an electronic format through the Electronic Data Input web site.

No violations pending.

Inspector's Signature

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 17, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		✓	
2.	Signs and Markers				
3.	Topsoil	~		✓	
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	~		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control	~		✓	
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 17, 2005 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee will re-submit the subsidence amendment for the 1st South panel. The map and text has been revised from the first submittal.

3. Topsoil

The topsoil piles were inspected with no signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and would function as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Water from equipment cleaning is being pumped to the sediment pond at the 4th east portals. Consol will be changing the method of how this water is being handled. Consol may have the water go under ground to the water sump or enlarge the sediment pond. The water from the sediment pond at the 4th east portals has not discharged.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected and no hazardous conditions were noticed during the inspection.

8. Noncoal Waste

The material storage area at the 4th east portals needed cleaning up of non-coal waste material.

14. Subsidence Control

Consol has committed in repairing the surface cracks from mining the 2nd South panel in August. During the next inspection, I will inspect this area.

18. Support Facilities, Utility Installations

No new support facilities have been added since the last inspection.